

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**



Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**



WV



F163




FIG 5







FIG 3A











BAYONET FOR LOCKING PLATENS  
TOGETHER

~~MOLD GUIDE PINS~~

## Tool Locks


Mold Pivot BRG

MOLD IN LOCKED  
TOGETHER  
POSITION

MOLD PIVOT CYL

## STATIONARY MOLD-HALF

2



3





FIGURE 11

TOP RAIL AND DRIVE ASSEMBLY

SIDE VIEW

④




FIG 12

VIEW OF DRIVE GEAR